Tree Island Industries Ltd.

Permit: 0184 / Due Date: September 30, 2023

13 - Four nail galvanizing m	achines associate	ed with No. 4 hot	nail galvanizing li	ne				
Particulate Matter								
Test Dates:	Apr 18, 2023	Apr 18, 2023	Apr 18, 2023					
Test Results:	0.0900 mg/m3	0.0900 mg/m3	0.0900 mg/m3					
Average of Test Results:	0.09 mg/m3							
Contaminant Permit Limit:	20.0000 mg/m3							
Test Result Comments:								
Flow Results:	321.000 m3/min	320.000 m3/min	321.000 m3/min					
Average of Flow Results:	320.667 m3/min							
Permitted Flow Limit:	305.00 m3/min							
Out of Compliance Explanation:	Cleaning of bags and repair of drive fan belt may be contributing factors. Other possibilities is having too many doors open on a nice/hot day allowed for less resistance to flow and the belt was set in such a way to allow max flow when doors were closed (increased resistance to flow)							
Plan of Action to Obtain Compliance:	Change the belt shiv to slow down the speed of the fan by 10% or install a variable speed drive							
Flow Result Comments:								
Zinc								
Test Dates:	Apr 18, 2023	Apr 18, 2023	Apr 18, 2023					
Test Results:	0.1500 mg/m3	0.5500 mg/m3	0.1000 mg/m3					
Average of Test Results:	0.267 mg/m3							
Contaminant Permit Limit:	7.0000 mg/m3							
Test Result Comments:								
Flow Results:	321.000 m3/min	320.000 m3/min	321.000 m3/min					
Average of Flow Results:	320.667 m3/min							
Permitted Flow Limit:	305.00 m3/min							
Out of Compliance Explanation:	Cleaning of bags and repair of drive fan belt may be contributing factors. Other possibilities is having too many doors open on a nice/hot day allowed for less resistance to flow and the belt was set in such a way to allow max flow when doors were closed (increased resistance to flow)							
Plan of Action to Obtain Compliance:	Change the belt shiv to slow down the speed of the fan by 10% or install a variable speed drive							
Flow Result Comments:								

Report date: 6/1/2023 5:21:26 PM Page 1 of 2

47 - Zinc tank associated with the No. 5 nail spin galvanizing line								
Particulate Matter								
Test Dates:	May 12, 2023	May 12, 2023	May 12, 2023					
Test Results:	0.1700 mg/m3	0.2300 mg/m3	2.1800 mg/m3					
Average of Test Results:	0.86 mg/m3							
Contaminant Permit Limit:	20.0000 mg/m3							
Test Result Comments:								
Flow Results:	105.000 m3/min	110.000 m3/min	107.000 m3/min					
Average of Flow Results:	107.333 m3/min							
Permitted Flow Limit:	230.00 m3/min							
Flow Result Comments:								
Zinc								
Test Dates:	May 12, 2023	May 12, 2023	May 12, 2023					
Test Results:	0.0170 mg/m3	0.0050 mg/m3	0.0070 mg/m3					
Average of Test Results:	0.01 mg/m3							
Contaminant Permit Limit:	7.0000 mg/m3							
Test Result Comments:								
Flow Results:	105.000 m3/min	110.000 m3/min	107.000 m3/min					
Average of Flow Results:	107.333 m3/min							
Permitted Flow Limit:	230.00 m3/min							
Flow Result Comments:								

Report date : 6/1/2023 5:21:26 PM Page 2 of 2